




REMACHADORA CCP 200
 Recorrido carrera 14,30 mm
 Tracción 725 Kg
 Presión de trabajo: ... 6 bar
 Consumo de aire:..... 2 l / remache
 Peso: 2,0 Kg

R510001	1A	BOQUILLA 4,8
R510002	1B	BOQUILLA 4
R510003	1C	BOQUILLA 3
R510004	1D	BOQUILLA 2,5
R510006	06-1	CAJA SUP.MORDAZA
R510007	06-2	CAJA INF. MORDAZA
R510008	7	MORDAZAS
R510009	8	EMPUJADOR MORDAZAS
R510010	9	ARANDELA
R510011	10	MUELLE
R510012	10A	JUNTA
R510013	11	PORTABOQUILLAS
R510014	12	TUERCA
R510015	13	JUNTA
R510016	14	JUNTA
R510017	15	BASTIDOR
R510018	16	PISTON ACEITE
R510019	17	JUNTA
R510020	18	ARANDELA
R510021	19	MUELLE RETORNO
R510022	20	ASA
R510023	21	CIERRE TAPA
R510024	22	ROSCA CIERRE
R510025	23	RECOGEDOR
R510026	24	PASADOR
R510027	25	JUNTA
R510028	26	JUNTA

R510029	27	TUERCA
R510030	28	AMORTIGUADOR
R510031	29	CILINDRO
R510032	30-1	VASTAGO PISTON
R510033	30-2	PLATO
R510034	30-3	TUERCA
R510035	30-4	PLATO GRANDE
R510036	30-5	PLATO PEQUEÑO
R510037	31A	BASE JUNTA PISTON
R510038	32	JUNTA
R510039	33	TAPA CILINDRO
R510040	35	LLAVE CALIBRADORA
R510041	36	LLAVE
R510042	37	PASADOR
R510043	38	PASADOR
R510044	39	EJE GATILLO
R510045	40	GATILLO
R510046	41	PASADOR
R510047	42	BUJE GATILLO
R510048	43A	JUNTA
R510049	44	EMPUJADOR
R510050	44A	MUELLE
R510051	45	VALVULA
R510052	45A	JUNTA
R510053	45B	COLLAR JUNTA
R510054	46	MUELLE
R510055	51	JUNTA
R510056	52	CIERRE VALVULA